


CARBON FLEX



CARBON FLEX

DESCRIPTION

PU metarial for computer cutting applications

SPECIFICATION

Size: 50 cm x 5 m **N.W**: 2 kg / roll

TRANSFER CONDITION

The following instructions are given as guideline only.

Temperature: 140°C (284°F) Pressing Time: 8 seconds

HOW TO USE

- 1) Cut an image on the PU in reverse by a plotter machine.
- 2) Weed the exess flex.
- 3) Place the image on a T-shirt.
- 4) Press it on at medium pressure for 8 seconds.
- 5) Remove the polyester backing film while it is warm peel.

SUITABLE FOR

Cotton, mixtures of polyester / cotton and polyester / acrylic or for similar textile.

Not suitable for treated and dyed garments.

NOTICE

All information given in this heet is based on our experience. We recommend you to perform a test prior to standart production.















8 seconds for pressing