

PU FLEX SHINE



PU FLEX SHINE

DESCRIPTION

PU material for computer cutting applications

SPECIFICATIONS

Size: 50 cm x 25 m

N.W: 5 kg / roll

TRANSFER CONDITIONS

The following instructions are given as guideline only.

Temperature: 150°C (302°F) **Pressing time:** 12 seconds

HOW TO USE

- 1) Cut an image on the PU in reverse by a plotter machine.
- 2) Weed the exess flex.
- 3) Place the image on a T-Shirt.
- 4) Press it on at medium pressure for 12 seconds.
- 5) Remove the polyester backing film while it is warm peel.

SUITABLE FOR

Cotton, mixtures of polyester / cotton and polyester / acrylic or for similar textile.

Not suitable for treated and dyed garments.

NOTICE

All information given in this sheet is based on our experience. We recommend you to perform a test prior to standart production.















°C (302°F) Medium, even pressure

12 seconds for pressing WARN